


UL International Germany GmbH

Frankfurter Strasse 229 · D-63263 Neu-Isenburg
Telefon +49 (0) 61 02 369-0 · Fax +49 (0) 61 02 369-280



CERTIFICATE OF COMPLIANCE

CERTIFICATE NUMBER: 20030530E234548

ISSUE DATE: 5-23-2003

Page 1 of 1

Issued to: HEINZ SOYER BOLZENSCHWEISSTECHNIK GMBH
INNINGER STR 14
82237 WOERTHSEE-ETTERSCHLAG GERMANY

Report Reference: E234548-20030523

This is to Certify that representative samples of: Transformer-Type Stud Welder
Three Phase Welding System, Models BSP 03 and BMK-8


Have been investigated by Underwriters Laboratories Inc.® in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: Standard for Transformer-Type Arc-Welding Machines:
UL551, 7th Edition, dated January 10, 1994, revised through and including
September 14, 1999

Canadian Standard for Arc Welding Equipment:
CSA C22.2 No. 60-M1990

Additional Information: ./.

Only those products bearing the UL Listing Mark for the US and Canada should be considered as being covered by UL's Listing and Follow-Up Service meeting the appropriate requirements for US and Canada.

The UL Listing Mark for the US and Canada generally includes: the UL in a circle symbol with "C" and "US" identifiers:  the word "LISTED"; a control number (may be alphanumeric) assigned by UL; and the product category name (product identifier) as indicated in the appropriate UL Directory.

LOOK FOR THE UL LISTING MARK ON THE PRODUCT

Engineer:

Frank Lehmann

UL International Germany GmbH

Review Engineer:

Brian Young

UL International Germany GmbH

Pursuant to the Corporate Services Agreement between UL International Germany GmbH and Underwriters Laboratories Inc. ("UL"), UL hereby accepts and issues this Certificate of Compliance. For questions in Germany, you may call +49-89-622703-0.